



ATB-URGENT CORROSION REFURBISHMENT TO BERTH 2 & 3 - 2021


URGENT- BERTH 2 & 3 CONDITIONS BEFORE CORROSION REFURBISHMENT



Sound steel pte ltd





Sound steel pte ltd




WET ABRASIVE BLASTING TO BERTH 2 & 3- SPOT BLAST CORRODED AREAS TO BARE METAL QUALITY




Sound steel pte ltd



Sound steel pte ltd



SALT & CHLORIDE TEST



1st COAT PAINTING (GREY)



Sound steel pte ltd



FINAL COAT PAINTING (WHITE))



Sound steel pte ltd



Sound steel pte ltd

