



PROJECT COMPLETION REPORT - HOT OIL

CORROSION UNDER INSULATION

S/NO	PO NO	ORDER DATE	PROJECT DESCRIPTION	START DATE	COMPLETION DATE	% COMPLETED	REMARKS
1	770-611421	16/10/2024	Hot Oil Corrosion Under Insulation	16/10/2024	30/10/2024	100%	Project Closed


Before Pictorial - HOT OIL CORROSION UNDER INSULATION






Wet Abrasive Blasting - HOT OIL CORROSION UNDER INSULATION





Painting - HOT OIL CORROSION UNDER INSULATION /HIGH TEMPERATURE PAINT





Inspection By ATB - En. Tamimi



Project Completion Report By: AST Corrosion Engineering Sdn. Bhd.